

PCN# 20200313000

Continuous Improvement on:

MitySOM-A10 Development Board PCA

Date: March 13, 2020

To: Purchasing Agents & Design Engineers

Dear Customer,

This is an initial announcement of a change to a product that is currently offered by Critical Link. The details of this change are on the following pages.

For questions regarding this notice, contact the Hardware Manager Bill Halpin (bill.halpin@critiallink.com).

Sincerely,

Critical Link, LLC

Phone: (315) 425-4045

Fax: (315) 425-4048



**PCN Number:** 20200313000**PCN Date:** March 13, 2020**Title:** PCIe Port Correction**Contact:** Bill Halpin**Phone:** (315) 425-4045**Ship Date:** n/a**Overview**

Change to MitySOM-A10 Development Board PCA is identified in the following sections.

**1 PCIe Port Correction****1.1 Description of Change**

Among the changes to the 2<sup>nd</sup> generation MitySOM-A10 development board (80-001218RI) the A10S module transceiver port signals to the PCIe interface transceiver connectors were reroute to swap with some of the FMC connector pins.

**1.2 Reason for Change**

The original PCIe design on the MitySOM-A10 Development Board PCA used transceivers not compatible with the Arria 10's PCIe Hard IP controller, resulting in a non-functional PCIe interface.

**1.3 Anticipated Impact on Form, Fit, Function (positive / negative)**

The 2<sup>nd</sup> generation MitySOM-A10 Development Board PCA has a fully functional PCIe port.

**1.4 Anticipated Impact on Quality or Reliability (positive / negative)**

There is no impact to Quality or Reliability with this change.

**2 Products Affected**

Details regarding the full revision history can be located in the MitySOM- A10s Revision History section on the Critical Link support site.

[https://support.criticallink.com/redmine/projects/mitysom\\_a10s/wiki](https://support.criticallink.com/redmine/projects/mitysom_a10s/wiki)

**Table 1: Products Affected**

Model Number	Starting PCA	Replacement PCA
n/a	80-001127RC-1	80-001218RI-3
n/a	80-001127RC-2	80-001218RI-3
n/a	80-001127RC-3	80-001218RI-3

See MitySOM-A10s Datasheet and Carrier Board Design Guide for migration options across the MitySOM- A10s family.

### 3 Document Revision History

Date	Version	Change Description
13-March-2020	1.0	Initial Version